

Contents

I. Report of Conservation works

Chapter 1 Process of the Dismantling Work	1
---	---

Chapter 2 Dismantling of Lower Platform

Section 1 Dismantling of the Upper Tiers(N19-N22)	2
---	---

Section 2 Dismantling of the Basement of the Lower Platform(N23-N25)	10
--	----

Chapter 3 Restoration Work

Section 1 Restoration of the South Stairway of the Central Sanctuary	16
--	----

Section 2 Bonding of Sandstone Blocks	18
---------------------------------------	----

Chapter 4 Survey of the Foundation

Section 1 Survey of the Digging Work	19
--------------------------------------	----

Section 2 Buried Pottery	24
--------------------------	----

Section 3 Ground Survey of the Foundation Soil around the Stone Lines in the Foundation	28
---	----

Chapter 5 Progress of Restoration Work

Section 1 Progress of Trial Assembly	29
--------------------------------------	----

Section 2 Reassembly of the Platform Basement	30
---	----

II. Articles

Chapter 1 Examination of Restoration Methods for the South Sanctuary of Western Prasat Top	31
--	----

Chapter 2 The Western Top Temple's Stone Blocks	49
---	----

Chapter 3 New Elements of Theravada Buddhism Found at Western Prasat Top	56
--	----